

Equipment Inspection Report

Inspection Date:

Course:

General Information

Make: JOHN DEERE	Model: 2500B PRO CUT
Serial Number: 095216	Year: 2015
<input checked="" type="checkbox"/> 2WD <input type="checkbox"/> 3WD <input type="checkbox"/> 4WD	Hours:

Accessories Included: KINDOT TRAILER – TIRES POOR

General Appearance

Front Body Panels	<input type="checkbox"/> Excellent Condition (no scratches) <input checked="" type="checkbox"/> Good Condition (minor scratches) <input type="checkbox"/> Average Condition (some scratches) <input type="checkbox"/> Poor Condition	Rear Body Panels	<input type="checkbox"/> Excellent Condition (no scratches) <input checked="" type="checkbox"/> Good Condition (minor scratches) <input type="checkbox"/> Average Condition (some scratches) <input type="checkbox"/> Poor Condition
Seat/Frame	<input checked="" type="checkbox"/> Excellent Condition <input type="checkbox"/> Good Condition (normal wear) <input type="checkbox"/> Average Condition (Minor tear) <input type="checkbox"/> Poor Condition	Wheels/Tires/Tracks	<input type="checkbox"/> Excellent Condition <input checked="" type="checkbox"/> Good Condition (normal wear) <input type="checkbox"/> Average Condition (worn) <input type="checkbox"/> Poor Condition
Canopy/Cab	<input type="checkbox"/> Excellent Condition <input type="checkbox"/> Good Condition <input type="checkbox"/> Average Condition <input type="checkbox"/> Poor Condition	Rollers/Reels/Decks Attachments	<input type="checkbox"/> Excellent Condition <input type="checkbox"/> Good Condition <input checked="" type="checkbox"/> Average Condition <input type="checkbox"/> Poor Condition (rusty)

Operator Station

Gauges	<input checked="" type="checkbox"/> Normal working condition <input type="checkbox"/> Not working <input type="checkbox"/> Missing	Machine Controls	<input checked="" type="checkbox"/> Normal working condition <input type="checkbox"/> Not working <input type="checkbox"/> Missing
Machine Frame	<input checked="" type="checkbox"/> Normal <input type="checkbox"/> Rusted <input type="checkbox"/> Broken	Brakes	<input type="checkbox"/> Normal working condition <input checked="" type="checkbox"/> Not working <input type="checkbox"/> Missing
Reels/Head	<input type="checkbox"/> 7 Blade <input type="checkbox"/> 11 Blade <input type="checkbox"/> 8 Blade <input type="checkbox"/> 14 Blade <input type="checkbox"/> 9 Blade <input type="checkbox"/> 15 Blade <input type="checkbox"/> 10 Blade <input type="checkbox"/> Rotary	Tines	<input type="checkbox"/> Excellent Condition <input type="checkbox"/> Average Condition <input checked="" type="checkbox"/> Needs Sharpening <input type="checkbox"/> Missing

Power Train

<p>Engine Type</p>	<p><input checked="" type="checkbox"/> Gasoline <input type="checkbox"/> Diesel <input type="checkbox"/> Electric MFG: Click or tap here to enter text. HP: Click or tap here to enter text.</p>	<p>Engine Condition</p>	<p><input checked="" type="checkbox"/> Normal working condition <input type="checkbox"/> Runs, normal wear/tear <input type="checkbox"/> Does not run <input type="checkbox"/> Bad Battery</p>
<p>PTO/Transmission</p>	<p><input checked="" type="checkbox"/> Normal working condition <input type="checkbox"/> Slips in drive <input type="checkbox"/> Reverse out <input type="checkbox"/> Does not move</p>	<p>Drive Belts</p>	<p><input checked="" type="checkbox"/> Normal working condition <input type="checkbox"/> Not working <input type="checkbox"/> Missing</p>
<p>Electric Motors</p>	<p><input type="checkbox"/> Normal working condition <input type="checkbox"/> Not working <input type="checkbox"/> Missing <input type="checkbox"/> N/A</p>	<p>Hydraulics</p>	<p><input checked="" type="checkbox"/> Normal working condition <input type="checkbox"/> Pump leaks <input type="checkbox"/> Hoses broken or leaks <input type="checkbox"/> Valve bank leaks</p>

Additional Comments:

Inspected by: _____